

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1




FIG. 2




FIG. 3

PRIOR ART




FIG. 4.1




FIG. 4.2




FIG. 5




FIG. 6




FIG. 7




FIG. 8.1




FIG. 8.2




FIG. 8.3




FIG. 9.1




FIG. 9.2




FIG. 10




FIG. 11.1




FIG. 11.2




FIG. 12.1

FIG. 12.2




FIG. 12.3




FIG. 12.1A




FIG. 12.2A




FIG. 12.3A




FIG. 13.1




FIG. 13.2




FIG. 14.1




FIG. 14.2




FIG. 15.1




FIG. 15.2






FIG. 16.2




FIG. 16.1








FIG. 17

**Title:** Fastening Assembly for Securing Bed Liner to Truck Bed  
**Applicant:** Ekawat Vitoorapakorn et al  
**Cust. No.:** 570 **Appl. No.:** 10/802,703 **Atty. Docket No.:** 602193-9








FIG. 22




FIG. 23